

# Product Safety Recall

## Kids II Rocking Sleepers

Sold at The Warehouse, The Baby Factory, and online through Mighty Ape between June 2016 and June 2018



Photo is representative. Your product may look different.

### Affected Kids II Sleepers:

Bright Starts Toucan Tango Rocking Sleeper  
Ingenuity Moonlight Rocking Sleeper  
Ingenuity Soothing Light Rocking Sleeper  
Ingenuity Dream Comfort Automatic Rocking Sleeper.

**Defect:** Product is potentially dangerous when instructions and warnings are not followed. Infants may roll from their back to their stomach or side if unrestrained.

**Hazard:** There is a risk of suffocation if the infant rolls from its back to stomach or side while unrestrained or if bedding or blankets are used with the product.

**What to do:** Consumers should stop using the product immediately. Contact Kids II for recall information and refund procedures.

For further information, please visit [www.kidsii.com](http://www.kidsii.com), send an email to [kidsii6091@stericycle.com](mailto:kidsii6091@stericycle.com), or call 0800 239 012 (Monday-Friday 8:00 AM - 5:00 PM). After contacting Kids II, consumers will be asked to render the product unusable, and to take a photograph as proof.

See [www.recalls.govt.nz](http://www.recalls.govt.nz) for  
New Zealand product recall information