

# PRODUCT SAFETY RECALL



## MILAZO BICYCLES: MODELS 417-427

Barcode #9401056207480 - #9401056207497 - #9401056207558 - #9401056207534 - #9401056207473

#9401056207565 - #9401056207527 - #9401056207503 - #9401056207510 - #9401056207466 - #9401056207541

Sold at the Warehouse Stores and online from April to July 2019.

**Defect:** The crank arm may be defective resulting in them coming loose or falling off.

**Hazard:** If the crank arm becomes loose or falls off while the bike is being ridden, the rider may lose control of the bicycle and fall or crash.

**What to do:** Stop using the bicycle and return it to your nearest "The Warehouse" store for a full refund – proof of purchase not required.

The Warehouse Ltd wishes to apologise to our customers for any inconvenience that this may cause.

**Contact details:** For more information please contact The Warehouse:

**Phone:** 0800 422 274

**Email:** [CustomerServiceTeam@thewarehouse.co.nz](mailto:CustomerServiceTeam@thewarehouse.co.nz)

**Online:** <http://www.thewarehouse.co.nz/red/>

**New Zealand Importer/Distributor**

The Warehouse Ltd  
PO Box 33470 Takapuna  
Auckland 0740  
New Zealand

thewarehouse 

Notice issue date: 15th July 2019

See [www.recalls.govt.nz](http://www.recalls.govt.nz) for other New Zealand consumer product recalls.

TWLWK51PRB